



1128

**2/7 ACE CRESCENT
TUGGERAH NSW 2259
PHONE 02 4352 2044
MVRL 54706**

Vehicle Condition Inspection Report

Date of Inspection:

Vehicle Make & Model

BOLWELL MK VII

Body Style

Coupe

Year

1965

VIN

N970478P

Odometer

7806 km

Summary of overall Vehicle Condition

Good

Fair

Poor

Engine/Exhaust

Engine Oil Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N	Tune Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N	Fuel System	<input checked="" type="radio"/> Y / <input type="radio"/> N	Thermostat	<input checked="" type="radio"/> Y / <input type="radio"/> N
Oil Leaks	Y / <input checked="" type="radio"/> N	Smoke	Y / <input checked="" type="radio"/> N	Fuel Leaks	Y / <input checked="" type="radio"/> N	Exhaust Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N
Engine Mounts	<input checked="" type="radio"/> Y / <input type="radio"/> N	Air Filter	<input checked="" type="radio"/> Y / <input type="radio"/> N	Radiator Hoses	<input checked="" type="radio"/> Y / <input type="radio"/> N	Exhaust Mounts	<input checked="" type="radio"/> Y / <input type="radio"/> N
Engine Noises	Y / <input checked="" type="radio"/> N	Drive Belts	<input checked="" type="radio"/> Y / <input type="radio"/> N	Water Pump	<input checked="" type="radio"/> Y / <input type="radio"/> N		
Exhaust Leaks	Y / <input checked="" type="radio"/> N	Emission System	<input checked="" type="radio"/> Y / <input type="radio"/> N	Coolant	<input checked="" type="radio"/> Y / <input type="radio"/> N		

Comments-

Transmission/Driveline

Automatic

Manual

Transmission	<input checked="" type="radio"/> Y / <input type="radio"/> N	Mounts	<input checked="" type="radio"/> Y / <input type="radio"/> N	Clutch Ops	<input checked="" type="radio"/> Y / <input type="radio"/> N	CV/Universal Joints	<input checked="" type="radio"/> Y / <input type="radio"/> N
Oil/Fluid Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N	Noises	Y / <input checked="" type="radio"/> N	Adjustment	<input checked="" type="radio"/> Y / <input type="radio"/> N	Drive shaft/Boots	<input checked="" type="radio"/> Y / <input type="radio"/> N
Shift Operation	<input checked="" type="radio"/> Y / <input type="radio"/> N	Inhibitor Switch	Y / <input checked="" type="radio"/> N	Linkages	<input checked="" type="radio"/> Y / <input type="radio"/> N	Final Drive	<input checked="" type="radio"/> Y / <input type="radio"/> N

Comments-

Steering/Suspension

Power Assistance

Yes

No

Steeringbox/Rack	<input checked="" type="radio"/> Y / <input type="radio"/> N	Power Steering	Y / <input checked="" type="radio"/> N	Wheel Bearings	<input checked="" type="radio"/> Y / <input type="radio"/> N	Wheel/Spare	<input checked="" type="radio"/> Y / <input type="radio"/> N
Oil Leaks	Y / <input checked="" type="radio"/> N	Shock Absorbers	<input checked="" type="radio"/> Y / <input type="radio"/> N	Tyre Wear	<input checked="" type="radio"/> Y / <input type="radio"/> N	Driveability	<input checked="" type="radio"/> Y / <input type="radio"/> N
Steering Linkage	<input checked="" type="radio"/> Y / <input type="radio"/> N	Bushes/Pivots	<input checked="" type="radio"/> Y / <input type="radio"/> N	Tyre Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N		

Comments-

Brakes

Operation	<input checked="" type="radio"/> Y / <input type="radio"/> N	Line Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N
Park Brake	<input checked="" type="radio"/> Y / <input type="radio"/> N	Hose Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N
Fluid Leads	Y / <input checked="" type="radio"/> N	Pedal Height	<input checked="" type="radio"/> Y / <input type="radio"/> N
Pads/Lining	<input checked="" type="radio"/> Y / <input type="radio"/> N	Pedal Rubbers	<input checked="" type="radio"/> Y / <input type="radio"/> N
ABS Check Light	Y / <input checked="" type="radio"/> N		

Electrical

Wiring	<input checked="" type="radio"/> Y / <input type="radio"/> N	Windscreen Wipers	<input checked="" type="radio"/> Y / <input type="radio"/> N
Headlights/Aim	<input checked="" type="radio"/> Y / <input type="radio"/> N	Battery/Starter Motor	<input checked="" type="radio"/> Y / <input type="radio"/> N
Exterior Lighting	<input checked="" type="radio"/> Y / <input type="radio"/> N	Charge Rate	<input checked="" type="radio"/> Y / <input type="radio"/> N
Indicators	<input checked="" type="radio"/> Y / <input type="radio"/> N	Horn	<input checked="" type="radio"/> Y / <input type="radio"/> N
Instrumentation	<input checked="" type="radio"/> Y / <input type="radio"/> N		

Comments-

Body

Structure	<input checked="" type="radio"/> Y / <input type="radio"/> N	Previous Repairs	<input type="radio"/> Y / <input checked="" type="radio"/> N	Door Locks	<input checked="" type="radio"/> Y / <input type="radio"/> N	Seats & Trim	<input checked="" type="radio"/> Y / <input type="radio"/> N
Corrosion	<input type="radio"/> Y / <input checked="" type="radio"/> N	Windscreen/Glass	<input checked="" type="radio"/> Y / <input type="radio"/> N	Door/Window Op	<input checked="" type="radio"/> Y / <input type="radio"/> N	Seat Belts	<input checked="" type="radio"/> Y / <input type="radio"/> N
Panel Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N	Paint Condition	<input checked="" type="radio"/> Y / <input type="radio"/> N	Windows Tinting	<input checked="" type="radio"/> Y / <input type="radio"/> N	Door Handles	<input checked="" type="radio"/> Y / <input type="radio"/> N

Comments- _____

Miscellaneous

Demister	<input checked="" type="radio"/> Y / <input type="radio"/> N	Heater	<input checked="" type="radio"/> Y / <input type="radio"/> N	Ability to run on alternative fuels	<input type="radio"/> Y / <input checked="" type="radio"/> N
Air Conditioner	<input type="radio"/> Y / <input checked="" type="radio"/> N	LPG Compliance	<input type="radio"/> Y / <input checked="" type="radio"/> N	Other	

Comments- _____

PRE-PURCHASE INSPECTION REPORT TERMS AND CONDITIONS

Report is visual only

1. This pre-purchase inspection report is not undertaken by Gosford Classic Car Museum but by a third party inspector and is based only on a visual and non-mechanical inspection of the condition of the specific items set out in this report form.
2. This report only advises on the condition of the vehicle at the time of inspection.

What the report does not cover

3. Supplementary Restraint or Air Bag Systems have been specifically excluded from the inspection due to the complexity of test procedures. Customers who are considering the purchase of a vehicle fitted with an SRS or Air Bag System are advised to refer the vehicle to an authorised service agent for system functionality
4. This report is not a substitute for a roadworthy test, which is a tolerance test. The customer acknowledges that receipt of a satisfactory condition report does not mean the vehicle will also pass a roadworthy test. This report is not a road worthy certificate and cannot be used as a roadworthy certificate.
5. This report does not advise on whether any manufacturer recall notices apply to the vehicle and it is your responsibility to check that the vehicle is not subject to a recall notice.

Purpose of the Report

6. You understand that this report is not intended to be a valuation of the vehicle, nor is it intended to be advice whether or not to purchase the vehicle. No warranties are made in relation to the value, performance or adequacy of the vehicle. The decision to purchase a vehicle is your own having regard to such matters as you consider relevant and having regard to your own circumstances and your own investigations and inquiries. Reliance on this report is subject to these terms and conditions.
7. Coastal Automotive Enterprises is not an agent or representative of Gosford Classic Car Museum.

Limitation of liability

8. Gosford Classic Car Museum is not responsible for carrying out the inspection, any services connected with such inspection or the contents of this report
9. Gosford Classic Car Museum and Coastal Automotive Enterprises will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection or for any defects that could reasonably be expected to have become evident by the dismantling or removal of parts of the vehicle or by inspection of any items not set out in the report form.
10. Except as expressly provided in this report, all terms, conditions, warranties, guarantees and statements whether express or implied, written, oral, statutory or otherwise, are excluded, other than terms which my by law may not be excluded (including the Australian Consumer Law).
11. To the full extent permitted by law, Gosford Classic Car Museum will only be liable to you pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law that cannot be excluded PROVIDED THAT, to the full extent permitted by law, any such liability of Gosford Classic Car Museum is limited at Gosford Classic Car Museums option to:
 - a. Replace or repair the relevant goods
 - b. Supplying goods equivalent to the relevant goods
 - c. Supplying the relevant services again; or
 - d. Paying the cost of such replacement, repairs or supply
 - e. **Governing Law**
12. This Report is subject to the laws of the State of New South Wales, Australia.

